



**1.1** Upstream face of Allen Road bridge from Thunderbowl Lanes bowling alley in Allen Park, looking downstream.



**1.2** Upstream face of Allen Road bridge in Allen Park, looking downstream. Note high water marks on bridge pier about six inches above flood levels.



**1.3** NBECD from pedestrian foot bridge at Intercity Baptist Church property in Allen Park, looking downstream.



**1.4** NBECD from pedestrian foot bridge at Intercity Baptist Church property in Allen Park, looking upstream.



**2.1** Downstream face of railroad bridge crossing near confluence with Reek Drain in Allen Park, looking upstream.



**2.2** Downstream face of railroad bridge crossing near confluence with Reek Drain in Allen Park, looking upstream.



**2.3** Reek Drain east of Southfield Freeway behind commercial property in Allen Park, looking downstream. Note drain is near bank-full conditions.



**2.4** Reek Drain through Cunningham Park in Allen Park, looking upstream. Note drain is near bank-full conditions and proximity of drain to nearby homes.



**3.1** Reeck Drain in Cunningham Park in Allen Park, looking downstream. Note heavy brush and vegetation present along overbanks and in main channel.



**3.2** Reeck Drain just east of Pelham Road in Allen Park, looking downstream. Note drain is near bank-full conditions.



**3.3** Reeck Drain culvert under Pelham Road in Allen Park, looking upstream. Note flood level is about six inches below the top of headwall.



**3.4** Street flooding on Jackson Avenue south of Van Born Road and west of Pelham Road in Taylor, looking south. Note flooding near top of curbs.



**4.1** Avalon Street near Jackson Street south of Van Born Road and west of Pelham Road in Taylor, looking east. Note flooding near top of curbs.




**4.1** Ziegler Street near intersection with Avalon Street south of Van Born Road and west of Pelham Road in Taylor, looking northeast. Note flooding is well above top of curbs and over sidewalks into front lawns.



**4.1** Ziegler Road near intersection with Avalon Road south of Van Born Road and west of Pelham Road in Taylor, looking northeast. Note flooding over driveway and near brick ledge.



**4.4** Ziegler Road near intersection with Avalon Road south of Van Born Road and west of Pelham Road in Taylor, looking southeast. Note flooding into front lawns and over driveway.



**5.1** Ziegler Road near intersection with Avalon Road south of Van Born Road and west of Pelham Road in Taylor, looking southeast. Note flooding into front lawns and over driveway.



**5.2** Mayfair Street south of Van Born Road and west of Pelham Road in Taylor, looking south. Note flood levels near top of curbs.



**5.3** Monroe Street bridge crossing over the NBECD in Dearborn Heights, looking upstream. Note flood levels were about one foot below low chord of bridge.



**5.4** NBECD near intersection of Monroe Street and Hanover Avenue in Dearborn Heights, looking downstream. Silt deposition observed about six inches above flood levels.



**6.1** Monroe Street bridge crossing over the NBEC D near Hanover Avenue in Dearborn Heights, looking south. High water marks on bridge abutments were about six inches higher than flood levels.



**6.2** NBEC D near Jackson Street in Dearborn Heights, looking south. High water marks on bridge abutments were about six inches higher than flood levels.



**6.3** NBEC D from Banner Street pedestrian foot bridge in Dearborn Heights, looking upstream. Silt deposition observed about six inches above flood levels.



**6.4** Upstream face of Beech-Daly Road bridge crossing over the NBEC D in Dearborn Heights near USGS stream gage, looking downstream.